

State of Utah DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil Gas and Mining

JOHN R. BAZA Division Director

Minerals Inspection Report

Reviewed

Report Date: 03/06/2014

Mine Name: Fox Canyon (5 acres)	Permit Number:	S/49/0080	Mine Status:	Active
Operator Name: Beck Construction	Inspection Date:	03/06/2014	Permit Fees:	Paid
Inspector(s): A. Abate	Inspection Time:	12:45	Bond Amount:	\$8,000
Attendee(s): Dana Beck	Weather:	cloudy	Bond Escalation:	
Inspection Purpose: Determine extent of reclamation work		Prior Inspection:not previously in		
Conclusions and Recommendations Mr. Beck will complete reclamation over the next few come back out to the site once the reclamation work the	weeks and apply for a partial		ne earthwork. We agree	d that I would

Mr. Beck will complete reclamation over the next few weeks and apply for a partial bond release for the earthwork. We agreed that I would come back out to the site once the reclamation work this year is complete and that will serve as the partial bond release inspection. He understands that there is a 3 year liability period on the vegetation. If the reseeding is successful sooner than 3 years, he will have the option of applying for the release on the remaining funds.


TP 7-8						
Elements of Inspection		Evaluated & Commented	Enforcement			
1.	Permits, Revisions, Transfer, Bonds					
The Division sent a letter to the operator requiring a bond escalation for this property, which is what prompted the inspection. The operator was perplexed that this site was permitted in the first place. The operation is alluvial sand and gravel. Regardless, the property is to be redeveloped into a residential subdivision as part of the Traverse Mountain subdivision. The operator intends to conduct reclamation prior to the redevelopment.						
2.	Public Safety (shafts, adits, trash, signs, highwalls)					
3.	Protection of Drainages/Erosion Control					
4.	Deleterious Material					
5.	Roads (maintenance, surfacing, dust control, safety)					
6.	Reclamation					
	The site consists of a flat pad and hillslope. Mr. Beck explained that the slope has been prepped for reclamation while the pad area will be the footprint for the condos.					
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)					
	The slope has been brought to an approximate 3:1 grade. Topsoil was salvaged and will be used to cover the slope prior to reseeding.					
8.	Soils					
9.	Revegetation	\boxtimes				
	The upper portion of the slope was already topsoiled and seeded. Vegetation has started to come in but there is not much in the general vicinity of this canyon other than grasses.					
10.	Other					

Inspector's Signature:


CC: Dana Beck dana@beckbeckutah.com

File: /E/FoxCanyon03062014.pdf


Mine: Inspected: 03/06/2014



The site is a barren hillslope that is a sand bar deposit near the Point of the Mountain area in Using the hilltop areas as a reference for surrounding native vegetation, the area consists of Utah County.



grasses only.



The slopes are graded and have been prepped to receive salvaged topsoil for seeding.



Permit area vicinity map.